3855 Lakewood Boulevard Long Beach, California 90846

September 13, 1978

C1-725-160

U. S. Bronze Powders, Inc. 4615 Ardine Street Cudahay, California 90201

DPM 439

Gentlemen:

This facility must, on occasion, reship your product:

ALUMINUM PASTE, #71

In order to insure our compliance with the Hazardous Materials Regulations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your product is a regulated or restricted article for shipment by surface or air modes of transport.

Should the product be regulated, please indicate:

- 1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
- 2. DOT Hazard Classification per Section 172.101, 49 CFR.
- Flash Point and Closed Cup method per Section 173.115, 49 CFR.
- 4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet, if available, indicating whether or not the product is photochemically reactive.

Your cooperation and prompt reply will be appreciated.

Very truly yours,

M. J. Veneroso, Dept. C1-725 (52-11)

Materials Handling & Packaging Engineering

Douglas Aircraft Company

WTJ:rc

Japa



FULLER-O'BRIEN DIVISION THE O'BRIEN CORPORATION

August 11, 1977

M. J. Veneroso, Dept. C1-726(52-11) Materials Handling & Packaging Engineering Douglas Aircraft Company 3855 Lakewood Blvd. Long Beach, California 90846

Re: C1-726-212

Dear Mr. Veneroso:

The items listed in your July 25 letter have not been manufactured for several years so should be considered obsolete except for:.

Material Safety Data Sheets for these are enclosed.

Sincerely,

FULLER-O'BRIEN DIVISION The O'Brien Corporation

Heich

Herman L. Leichel

Sales Administration

Industrial Finishes Division

HLL:dm

encls.

| Aluminum Paste, #1571 🙉 🖔 | DPM 439 (No longer manufactured) |
|---------------------------------|-------------------------------------|
| Wood Filler, #1206 | DPM 1063-3 (No longer manufactured) |
| د Coating, #171-C-80 | DPM 1258 |
| په Glazing Compound #163-W-53 م | DPM 2860 |
| Varnish, #56-C-279 | DPM 5289 (No longer manufactured) |
| ې Primer, #162-B-4 | DPM 5405 |
| _Catalyst, #75X-24 | DPM 5405 |
| Coating, #175-F-3 | DPM 5507 (No longer manufactured) |